



Opel – соотношение сигналов от датчиков коленвала и распредвала


Opel Astra F 1993 1.4 C14NZ




[opel_astra_f_1993_1.4_c14nz.mwf](#)




Opel Vectra B 1998 1.6 XEL




[opel_vectra_b_1998_1.6_xel.mwf](#)




Opel Vivaro F9Q 760



[opel_vivaro_f9q_760.mwf](#)



Opel Zafira 1999 1.8



[opel_zafira_1999_1.8.mwf](#)

